

Kodak i1400 Series Scanners Software Release Notes

Version CD 3.09 Summary

Purpose of Release: This is a CPE release of drivers for the Kodak i1400 Series Scanners.

Note: When installing a Kodak i1400 scanner on a host PC for the first time the Full Install CD (shipped with the scanner) must be used. If the InstallSoftware_v3.xx.exe driver installer is used for a new installation the Kodak Smart Touch application will not be installed. The InstallSoftware_v3.xx.exe may be used to update a host PC that used an Install CD Version 1.xx for its first install.

Date:	October 16th, 2013
CD Version:	3.09
Smart Touch	1.7.82
Twain:	12.10
Driver.dll:	1.7
Twaingui:	5.23
Hippo.dll:	52.3
Device.dll:	1.3
DeviceManager.dll:	3.9
ISIS driver:	1.1.11310.4003
Flatbed4/bundle:	2.16
Flatbed3/bundle	2.16

New Driver Features:

None

Smart Touch Features Fixed

None

Driver Issues Fixed:

- Reduce the size of the hole that hole fill fills in and how far it searches for holes from the edge of the image.
- Difference in image processing between scanners
- Foreground Bolding not working
- Peregrine A4 Legal, - SVT B&W profiles causing TWCC_Operationerror (0x5)
- Save logs is taking 3X the time the prior cd release
- Unable to scan using Capture Pro v4.1 with i1400 scanner
- Unable to perform any Calibrations. Message received is "No paper found in input tray"
- Old profiles do not work with new arch driver
- Imprinter template items are missing
- Attempting to print with text string containing special characters results in lexexe.exe error
- OverrideWarmupTime alteration is broken in new architecture

Known Issues:

Do not upgrade to this version if you are using one of the following alterations as they are not supported in this version:

- DisableTraySensor
- KeepMultifeedImage
- LongDoc80
- JumboSuperLength
- AutoStartOnPaperDetect