

Alaris E1000 Series Scanners Release Notes

Version CD 3.3 Summary

Purpose of Release: This is an updated release of the TWAIN and ISIS drivers for E1000 scanners which changes the driver inquiry data from Alaris E1000 to Kodak E1000.

ONLY INSTALL THIS DRIVER VERSION IF THE SCANNING APPLICATION IS KNOWN TO SUPPORT THE KODAK BRANDED DRIVERS.

Note: The drivers only file, [InstallSoftware_E1000_v3.3.exe](#), does not include user guides or the required Microsoft .NET Framework files. This file can be used as the initial installation on a computer, as long as the .NET Framework has been installed. Windows 7, 8.1 and 10 include as standard the required .NET Framework.

The ISO image [CD_WINDOWS_ISO_E1000_v3.3.zip](#) is required for silent driver installation or an advanced (selectable) installation. Execute **set_up.exe /s** from the root of the ISO via the command line in order perform a silent/unattended install.

Instructions for installing drivers using the ISO file:

For Windows 8.1 and 10 OS, mount the ISO file as a drive (right click on the ISO file and select Mount). If Mount is not available in the list of options, right click on the ISO file, select Properties and change the Opens With to Windows Explorer and click OK. Mount will now appear with the right click of the ISO file.

For Windows 7 OS, either the ISO file has to be mounted as a drive or the ISO contents extracted to a folder using a 3rd party software tool. Software Tool providers (tools have not been tested and are not supported by the Kodak Alaris team, customers have reported that (7-zip, winrar, winiso)) offer such capability.

| | |
|---------------------------|------------------------|
| Date: | June 5, 2020 |
| CD Version: | 3.3 |
| Twain: | 19.1 |
| Driver.dll: | 3.4 |
| Twaingui: | 12.11 |
| Hippo.dll: | 52.8 |
| Device.dll: | 3.3 |
| DeviceManager.dll: | 3.2 |
| ISIS driver: | 1.0.12005.11005 |
| SVT: | 19.1 |
| | |
| TWAIN Standard | 2.4 |

Alaris E1000 Series Scanners Release Notes

Operating System Support

Windows

WINDOWS 7 SP1 32-bit and 64-bit
WINDOWS 8.1 32-bit and 64-bit
WINDOWS 10 32 bit (Versions: 1803,1809,1903,1909,2004,20H2)
WINDOWS 10 64 bit (Versions: 1809,1903,1909,2004,20H2)
WINDOWS SERVER 2012 R2 (64-bit)
WINDOWS SERVER 2016 (64-bit)

Linux - (Intel/AMD x86/64-bit processors only)

Ubuntu 16.04 32-bit and 64-bit
Ubuntu 18.04 64-bit
Open SUSE 11.3 (i586) 32-bit
Open SUSE LEAP 15.1 64-bit
SUSE Linux Enterprise Desktop 12.2 64-bit
SUSE Linux Enterprise Desktop 15 SP1 for 64-bit
Neokylin-NKLD-V7_U2-ZX64-REL-build54
NeoKylin-Live-Desktop-6.0-x86_64-B060-20160822
NeoKylin-Linux-Desktop-6.0-x86_64-B045-20141201 64-bit
NeoKylin-Linux-Desktop-6.0 i586 32-bit

New Driver Features:

1. Rebrand driver from Alaris to Kodak.

Issues Fixed:

None

Known Issues:

None

Alaris E1000 Series Scanners Release Notes

Version CD 2.1 Summary

Purpose of Release: This is a general release to the drivers for the Alaris E1000 Scanners for US Energy Star 3.0 standard and to fix some customer reported issues.

Note: The drivers only file, [InstallSoftware_E1000_v2.1.exe](#), does not include user guides or the required Microsoft .NET Framework files. This file can be used as the initial installation on a computer, as long as the .NET Framework has been installed. Windows 7, 8.1 and 10 include as standard the required .NET Framework.

The ISO image [CD_WINDOWS_ISO_E1000_v2.1.zip](#) is required for silent driver installation or an advanced (selectable) installation. Execute **set_up.exe /s** from the root of the ISO via the command line in order perform a silent/unattended install.

Instructions for installing drivers using the ISO file:

For Windows 8.1 and 10 OS, mount the ISO file as a drive (right click on the ISO file and select Mount). If Mount is not available in the list of options, right click on the ISO file, select Properties and change the Opens With to Windows Explorer and click OK. Mount will now appear with the right click of the ISO file.

For Windows 7 OS, either the ISO file has to be mounted as a drive or the ISO contents extracted to a folder using a 3rd party software tool. Software Tool providers (tools have not been tested and are not supported by the Kodak Alaris team, customers have reported that (7-zip, winrar, winiso)) offer such capability.

| | |
|---------------------------|------------------------|
| Date: | July 29, 2019 |
| CD Version: | 2.1 |
| Twain: | 18.0 |
| Driver.dll: | 2.1 |
| Twaingui: | 11.0 |
| Hippo.dll: | 52.8 |
| Device.dll: | 2.0 |
| DeviceManager.dll: | 2.0 |
| ISIS driver: | 1.0.11907.26001 |
| SVT: | 17.2.1 |

| | |
|-----------------------|------------|
| TWAIN Standard | 2.4 |
|-----------------------|------------|

Alaris E1000 Series Scanners Release Notes

Operating System Support

Windows

WINDOWS 7 SP1 32-bit and 64-bit
WINDOWS 8.1 32-bit and 64-bit
WINDOWS 10 32 bit (Versions: 1803)
WINDOWS 10 64 bit (Versions: 1809,1903)
WINDOWS SERVER 2012 R2 (64-bit)
WINDOWS SERVER 2016 (64-bit)

Linux - (Intel/AMD x86/64-bit processors only)

Ubuntu 16.04 32-bit and 64-bit
Ubuntu 18.04 64-bit
Open SUSE 11.3 (i586) 32-bit
Open SUSE LEAP 15.1 64-bit
SUSE Linux Enterprise Desktop 12.2 64-bit
SUSE Linux Enterprise Desktop 15 SP1 for 64-bit
Neokylin-NKLD-V7_U2-ZX64-REL-build54
NeoKylin-Live-Desktop-6.0-x86_64-B060-20160822
NeoKylin-Linux-Desktop-6.0-x86_64-B045-20141201 64-bit
NeoKylin-Linux-Desktop-6.0 i586 32-bit

New Driver Features:

2. SAGE-1337 – Support Energy Star 3.0 standard. Change maximum allowable timeout for Power Saver to 120 minutes.

Issues Fixed:

1. SAGE-1453 – Supported Flatbeds do not return to "home" position after scanning; when TWAIN application sets CAP_AUTOSCAN=False.

Known Issues:

None