

## **Kodak i4x50 Series Scanners ISIS Driver Update Release Notes** **ISIS Driver Version eki4x50\_1.1.12010.28009 Summary**

**Purpose of Release:** This update corrects 1 issue found with the ISIS driver related to an application determining if physical imprinter. See Improvements below for more detail.

**Date:** June 15, 2021

### **New Features from version eki4x50\_1.1.12010.28009:**

1. none

### **Improvements from version eki4x50\_1.1.12010.28009:**

1. DIAS-2317: with a Kofax VRS scanning application, sporadically returned error - 4778 (Invalid command operation code).

Root Cause: the ISIS driver is telling the scanner to update the Power Off timer setting while enabled which is not allowed and this results in the error to be reported to the application.

Solution: The ISIS driver is ignoring the attempt to set the Power Off timer when the system is enabled.

### **Supported Models:**

- This driver has been tested and approved for use for uses with Kodak i4x50 scanners with Kofax VRS enabled applications

### **Notes:**

- The previous versions of the ISIS driver do not need to be uninstalled before installing this update. If the previous version is uninstalled, then this update will install the full version of the ISIS driver correctly.
- This ISIS driver update should be installed after the installation of the scanner drivers from CD 4.2.