# **DVD Version 05.01.00 Summary**

**Purpose of Release:** This is a general release to the Host CD for the Kodak i4250, i4650 and i4850 scanners that has User Guide updates and an updated ISIS driver Update for December 2022 is that Windows 10 and 11 22H2 releases are supported with no changes required.

**Note:** The drivers only file, InstallSoftware\_i4x50\_v5.1.exe, does not include user guides or the required Microsoft .net framework files. This file can be used as the initial installation on a computer as long as .net framework has been installed. Windows 8.1,10 and 11 include as standard the required .net framework.

The installation media ISO image, DVD\_WINDOWS\_ISO\_i4x50\_v5.1.iso, is required for silent driver installation, advanced (selectable) installation. Execute set\_up.exe /s from the root of the ISO via the command line in order perform a silent/unattended install.

Instructions for installing drivers using the ISO file: For Windows 8.1,10 and 11, mount the ISO file as a drive. (right click on the ISO file and select Mount)

Date: May 11, 2022 (updated March 2023)

### Versions:

| TWAIN driver:         | 23.0           |
|-----------------------|----------------|
| Driver                | 5.1            |
| DriverUI              | 16.5           |
| Imageprocesing        | 52.12          |
| Device                | 4.0            |
| Devicemanager         | 8.0            |
| ISIS driver:          | 1.1.12109.8001 |
| Scan Validation Tool: | 23.11          |
| WIA:                  | 15.6           |

# **Required Scanner Firmware:**

Recommended Scanner Firmware Version: 21.10.01

2.5

# TWAIN Standard

# **Supported Operating Systems:**

#### (Windows)

WINDOWS 11 (Original release 21H2and 22H2) 64-bit WINDOWS 10 64 bit (Versions:1803,1809,1903,1909, 2004, 20H2,21H1,21H2,22H2) WINDOWS 10 32 bit (Versions:1709,1803,1809,1903,1909, 2004, 20H2,21H1,21H2,22H2) WINDOWS 8.1 32 bit (no longer tested by Kodak Alaris – March 2023) WINDOWS 7 SP1 32 bit & 64 bit (no longer tested by Kodak Alaris – March 2022)

(Linux - (Intel/AMD x86/64 bit processors only)) Ubuntu 20.04 64-bit Ubuntu 18.04 64-bit Ubuntu 16.04 64-bit and 32-bit

Open SUSE 13.2 (i586) 32-bit

Alaris, a Kodak Alaris business 336 Initiative Drive, Rochester, NY 14624

Open SUSE LEAP 15.2 64-bit SUSE Linux Enterprise Desktop 12.2 64-bit SUSE Linux Enterprise Desktop 15 SP1 for 64 bit Neokylin-NKLD-V7\_U2-ZX64-REL-build54

# **Supported Models:**

Kodak i4250, Kodak i4650, Kodak i4850

# New Features for CD 5.x.x:

1. none

# **Improvements from CD 5.x.x:**

- 1. DIAS-2113,2234 -When scanner properly detects and displays a multifeed on OCP, it takes 10+ seconds till this appears on PC
- 2. DIAS-2317: with a Kofax VRS scanning application, sporadically returned error -4778 (Invalid command operation code).
- 3. DIAS-2696 ISIS logs become very large due to debug sometime not disabling

# **Known Issues:**

- 1. DIAS-1250: Using ISIS driver with Scan Validation Tool, when Transport Timeout is set to Pause Scanning or Pause Wait for Paper, the stop button on the scanner must be used to end the job as the Stop button in SVT will not work.
- 2. DIAS-524: PC out of memory error when scanning long (thousands of documents) without disabling.
  - There is a workaround based on customer scanning parameters. Contact the Kodak Alaris service organization for more information.

# Notes:

# **DVD Version 04.05.00 Summary**

**Purpose of Release:** This is a general release to the Host CD for the Kodak i4250, i4650 and i4850 scanners which address a problem for a time delay after a multifeed occurs.

The installation media ISO image, DVD\_WINDOWS\_ISO\_i4x50\_v4.5.iso, is required for silent driver installation, advanced (selectable) installation. Execute set\_up.exe /s from the root of the ISO via the command line in order perform a silent/unattended install.

Instructions for installing drivers using the ISO file: For Windows 8.1 and 10 OS, mount the ISO file as a drive. (right click on the ISO file and select Mount)

Date: October 12,2020

# Versions:

| TWAIN driver:          | 18.0            |
|------------------------|-----------------|
| Driver                 | 4.2             |
| DriverUI               | 11.0            |
| Imageprocesing         | 52.12           |
| Device                 | 3.0             |
| Devicemanager          | 7.3             |
| ISIS driver:           | 1.1.11904.16001 |
| Scan Validation Tool:  | 17.2.1          |
| WIA:                   | 9.0             |
| Kodak Capture Pro LE   | No Longer on CD |
| Buttonapp (SmartTouch) | No Longer on CD |
|                        |                 |

# **Required Scanner Firmware:**

Recommended Scanner Firmware Version: 21.04.01

**TWAIN Standard** 2.4

# **Operating Systems (not a complete list of supported OS, see specifications page):**

WINDOWS 11 (Original release 21H2) WINDOWS 8.1 32 bit WINDOWS 10 32 bit (up to and including 21H1) WINDOWS 10 64 bit (up to and including 21H1)

(Linux - (Intel/AMD x86/64 bit processors only)) Ubuntu 18.04 64-bit Ubuntu 16.04 64-bit and 32-bit Open SUSE 11.3 (i586) 32-bit Open SUSE LEAP 15.1 64-bit SUSE Linux Enterprise Desktop 12.2 64-bit SUSE Linux Enterprise Desktop 15 SP1 for 64 bit Neokylin-NKLD-V7\_U2-ZX64-REL-build54 NeoKylin-Live-Desktop-6.0-x86\_64-B060-20160822 NeoKylin-Linux-Desktop-6.0 i586 32-bit

# **Supported Models:**

Kodak i4250, Kodak i4650, Kodak i4850

# New Features from CD 4.2.0:

1. no

# **Improvements from CD 4.2.0:**

2. DIAS-2334 – slow response (10 seconds) when a multifeed message is reported to the driver from the scanner.

### **Known Issues:**

- 3. DIAS-1250: Using ISIS driver with Scan Validation Tool, when Transport Timeout is set to Pause Scanning or Pause Wait for Paper, the stop button on the scanner must be used to end the job as the Stop button in SVT will not work.
- 4. DIAS-524: PC out of memory error when scanning long (thousands of documents) without disabling.
  - There is a workaround based on customer scanning parameters. Contact the Kodak Alaris service organization for more information.

### Notes:

# DVD Version 04.02.00 Summary

**Purpose of Release:** This is a general release to the Host CD for the Kodak i4250, i4650 and i4850 scanners that has multiple updates to address problems that result from changes to Windows 10 and to support the Energy Star 3.0 standard.

**Note:** The drivers only file, <u>InstallSoftware\_i4x50\_v4.2exe</u>, does not include user guides or the required Microsoft .net framework files. This file can be used as the initial installation on a computer as long as .net framework has been installed. Window 7,8.1 and 10 include as standard the required .net framework.

The installation media ISO image, <u>DVD\_WINDOWS\_ISO\_i4x50\_v4.2.iso</u>, is required for silent driver installation, advanced (selectable) installation. Execute set\_up.exe /s from the root of the ISO via the command line in order perform a silent/unattended install.

# Instructions for installing drivers using the ISO file:

For Windows 8.1 and 10 OS, mount the ISO file as a drive. (right click on the ISO file and select Mount) For Windows 7 OS, either the ISO file has to be mounted as a drive or the ISO contents extracted to a folder using a 3<sup>rd</sup> party software tool. Software Tool providers (tools have not been tested and are not supported by the Kodak Alaris team, customers have reported that (7-zip, winrar, winiso) offer such capability.

# Date: July 23, 2019

# Versions:

| TWAIN driver:          | 18.0            |
|------------------------|-----------------|
| Driver                 | 4.1             |
| DriverUI               | 11.0            |
| Imageprocesing         | 52.12           |
| Device                 | 3.0             |
| Devicemanager          | 7.1             |
| ISIS driver:           | 1.1.11904.16001 |
| Scan Validation Tool:  | 17.2.1          |
| WIA:                   | 9.0             |
| Kodak Capture Pro LE   | No Longer on CD |
| Buttonapp (SmartTouch) | No Longer on CD |
|                        |                 |

# **Required Scanner Firmware:**

Recommended Scanner Firmware Version: 19.04.01

# TWAIN Standard

# **Drivers tested on Operating Systems:**

#### (Windows)

WINDOWS 7 SP1 32 bit & 64 bit WINDOWS 8.1 32 bit WINDOWS 10 32 bit (Versions:1709,1803,1809,1903,1909, 2004, 20H2) WINDOWS 10 64 bit (Versions:1803,1809,1903,1909, 2004, 20H2)

2.4

(Linux - (Intel/AMD x86/64 bit processors only))

Ubuntu 18.04 64-bit Ubuntu 16.04 64-bit and 32-bit Open SUSE 11.3 (i586) 32-bit Open SUSE LEAP 15.1 64-bit SUSE Linux Enterprise Desktop 12.2 64-bit SUSE Linux Enterprise Desktop 15 SP1 for 64 bit Neokylin-NKLD-V7\_U2-ZX64-REL-build54 NeoKylin-Live-Desktop-6.0-x86\_64-B060-20160822 NeoKylin-Linux-Desktop-6.0-x86\_64-B045-20141201 64-bit NeoKylin-Linux-Desktop-6.0 i586 32-bit

# **Supported Models:**

Kodak i4250, Kodak i4650, Kodak i4850

# New Features from CD 2.0:

5. DIAS-1826 – Support Energy Star 3.0 standard. Change maximum allowable timeout for Power saver to 120 minutes.

# **Improvements from CD 2.0:**

1. DIAS-1820 – Installer address issue with some HP Elite computers that has a directory C:\Windows\Sysnative present in the Operating system.

# **Known Issues:**

- 2. DIAS-1250: Using ISIS driver with Scan Validation Tool, when Transport Timeout is set to Pause Scanning or Pause Wait for Paper, the stop button on the scanner must be used to end the job as the Stop button in SVT will not work.
- 3. DIAS-524: PC out of memory error when scanning long (thousands of documents) without disabling.
  - There is a workaround based on customer scanning parameters. Contact the Kodak Alaris service organization for more information.

# Notes:

# **DVD Version 02.00.00 Summary**

**Purpose of Release:** This is a general release to the Host CD for the Kodak i4250, i4650 and i4850 scanners that has multiple updates to address problems that result from changes to Windows 10.

**Note:** The drivers only file, <u>InstallSoftware\_i4x50\_v2.0.exe</u>, does not include user guides or the required Microsoft .net framework files. This file can be used as the initial installation on a computer as long as .net framework has been installed. Window 7,8.1 and 10 include as standard the required .net framework.

The installation media ISO image, <u>DVD\_WINDOWS\_ISO\_i4x50\_v2.0.iso</u>, is required for silent driver installation, advanced (selectable) installation.

# Instructions for installing drivers using the ISO file:

For Windows 8.1 and 10 OS, mount the ISO file as a drive. (right click on the ISO file and select Mount) For Windows 7 OS, either the ISO file has to be mounted as a drive or the ISO contents extracted to a folder using a 3<sup>rd</sup> party software tool. Software Tool providers (tools have not been tested and are not supported by the Kodak Alaris team, customers have reported that (7-zip, winrar, winiso) offer such capability.

# Date: May 4, 2018

### Versions:

| TWAIN driver:          | 16.0            |
|------------------------|-----------------|
| Driver                 | 2.0             |
| DriverUI               | 8.12            |
| Imageprocesing         | 52.12           |
| Device                 | 1.12            |
| Devicemanager          | 1.10            |
| ISIS driver:           | 1.1.11804.26001 |
| Scan Validation Tool:  | 14.21           |
| WIA:                   | 7.9             |
| Kodak Capture Pro LE   | No Longer on CD |
| Buttonapp (SmartTouch) | No Longer on CD |
|                        |                 |

# **Required Scanner Firmware:**

Recommended Scanner Firmware Version: 18.05.01

# **Supported Operating Systems:**

WINDOWS 7 SP1 WINDOWS 7 SP1 x64 Edition WINDOWS 8 WINDOWS 8 x64 Edition WINDOWS 8.1 WINDOWS 8.1 x64 Edition WINDOWS 10 WINDOWS 10 x64 Edition

# **Supported Models:**

Kodak i4250, Kodak i4650, Kodak i4850

# New Features from CD 1.11.00:

- 1. SAGE-111 Changed message text from "The scanner is in use by someone else. Make sure the scanner is not currently in use and try again." to "The scanner is in use by another application or someone else. Make sure the scanner is not currently in use and try again."
- 2. SAGE-507 Change SVT to default to twaindsm (provided by TWAIN working group) instead of twain (provided by Windows OS).
- 3. SAGE-735 Add silent install support for set\_up.exe in root directory of CD

# **Improvements from CD 1.11.00:**

- 1. DIAS-1441, DIAS-1452 Twain Driver will not connect with Windows 10 Creator v1709
- 2. CPSOLSTS-237 –Smart Touch buttons do not work with Windows 10 Creator v1709
- 3. DIAS-1478 Installation shows "not enough space" with 3TB harddrive
- 4. DIAS-1519 Power Off Timer is not being sent to scanner when Power Off is disabled/enabled

# **Known Issues:**

- 1. DIAS-1250: Using ISIS driver with Scan Validation Tool, when Transport Timeout is set to Pause Scanning or Pause Wait for Paper, the stop button on the scanner must be used to end the job as the Stop button in SVT will not work.
- 2. DIAS-524: PC out of memory error when scanning long (thousands of documents) without disabling.
  - There is a workaround based on customer scanning parameters. Contact the Kodak Alaris service organization for more information.

# Notes:

# **DVD Version 1.11.00 Summary**

**Purpose of Release:** This is a general release to the Host CD for the Kodak i4250, i4650 and i4850 scanners that removes SmartTouch and Capture Pro LE from the installation media and changes these applications to be internet downloads.

Instructions for installing drivers using the ISO file:

For Windows 8.1 and 10 OS, mount the ISO file as a drive. (right click on the ISO file and select Mount) For Windows 7 OS, either the ISO file has to be mounted as a drive or the ISO contents extracted to a folder using a 3<sup>rd</sup> party software tool. Software Tool providers (tools have not been tested and are not supported by the Kodak Alaris team, customers have reported that (7-zip, winrar, winiso) offer such capability.

Date: September 19, 2017

### Versions:

| TWAIN driver:          | 14.7            |
|------------------------|-----------------|
| Driver                 | 1.17            |
| ISIS driver:           | 1.1.11608.24001 |
| Scan Validation Tool:  | 14.13           |
| WIA:                   | 7.1             |
| Kodak Capture Pro LE   | No Longer on CD |
| Buttonapp (SmartTouch) | No Longer on CD |

#### **Required Scanner Firmware:**

Recommended Scanner Firmware Version: 17.09.01

#### **Supported Operating Systems:**

WINDOWS 7 SP1 WINDOWS 7 SP1 x64 Edition WINDOWS 8 WINDOWS 8 x64 Edition WINDOWS 8.1 WINDOWS 8.1 x64 Edition WINDOWS 10 WINDOWS 10 x64 Edition

# **Supported Models:**

Kodak i4250, Kodak i4650, Kodak i4850

# New Features from CD 1.7.1:

- 1. DIAS-1225 Remove SmartTouch from installation media
- 2. DIAS-1226 Remove Capture Pro LE from installation media
- 3. DIAS-1284 Update Installer with link to Smart Touch and Capture Pro LE internet downloadable files.

# **Improvements from CD 1.7.1:**

Page | 9 Controlled

1. DIAS-1126-Address issue with Windows VM using USB Redirection

#### **Known Issues:**

- 1. DIAS-1250: Using ISIS driver with Scan Validation Tool, when Transport Timeout is set to Pause Scanning or Pause Wait for Paper, the stop button on the scanner must be used to end the job as the Stop button in SVT will not work.
- 2. DIAS-524: PC out of memory error when scanning long (thousands of documents) without disabling.
  - There is a workaround based on customer scanning parameters. Contact the Kodak Alaris service organization for more information.

#### Note:

When installing a Kodak i4x50 Scanner on a host PC for the first time the Full Install CD (shipped with the scanner) or the ISO file must be used. The InstallSoftware\_v1.11.00 may be used to update a host PC that used an Install CD Version V1.xx for its first install.

# **DVD Version 1.07.01 Summary**

**Purpose of Release:** This is a general release to the drivers for the Kodak i4250, i4650 and i4850 scanners which adds feature and fixes problems.

Date: August 3, 2017

### Versions:

| TWAIN driver:          | 15.2              |
|------------------------|-------------------|
| Driver                 | 1.17              |
| ISIS driver:           | 1.1.11608.24001   |
| Scan Validation Tool:  | 14.4              |
| WIA:                   | 6.15              |
| Kodak Capture Pro LE   | 5.2.2.14.13200    |
| Buttonapp (SmartTouch) | 1.8.68.476.161128 |

#### **Required Scanner Firmware:**

Recommended Scanner Firmware Version: 17.07.01

### **Supported Operating Systems:**

WINDOWS 7 SP1 WINDOWS 7 SP1 x64 Edition WINDOWS 8 WINDOWS 8 x64 Edition WINDOWS 8.1 WINDOWS 8.1 x64 Edition WINDOWS 10 WINDOWS 10 x64 Edition

#### **Supported Models:**

Kodak i4250, Kodak i4650, Kodak i4850

#### New Features from CD 1.7.0:

1. DIAS-1106: Change Image Calibration to License Level 1

#### **Improvements from CD 1.4.1:**

1. none

#### **Known Issues:**

- 1. DIAS-1250: Using ISIS driver with Scan Validation Tool, when Transport Timeout is set to Pause Scanning or Pause Wait for Paper, the stop button on the scanner must be used to end the job as the Stop button in SVT will not work.
- 2. DIAS-524: PC out of memory error when scanning long (thousands of documents) without disabling.
  - There is a workaround based on customer scanning parameters. Contact the Kodak Alaris service organization for more information.

# **DVD Version 1.07 Summary**

**Purpose of Release:** This is a general release to the drivers for the Kodak i4250, i4650 and i4850 scanners which adds feature and fixes problems.

Date: March 02, 2017

### Versions:

| TWAIN driver:          | 15.2              |
|------------------------|-------------------|
| Driver                 | 1.16              |
| ISIS driver:           | 1.1.11608.24001   |
| Scan Validation Tool:  | 14.4              |
| WIA:                   | 6.15              |
| Kodak Capture Pro LE   | 5.2.2.14.13200    |
| Buttonapp (SmartTouch) | 1.8.68.476.161128 |

#### **Required Scanner Firmware:**

Recommended Scanner Firmware Version: 17.01.03

### **Supported Operating Systems:**

WINDOWS 7 SP1 WINDOWS 7 SP1 x64 Edition WINDOWS 8 WINDOWS 8 x64 Edition WINDOWS 8.1 WINDOWS 8.1 x64 Edition WINDOWS 10 WINDOWS 10 x64 Edition

#### **Supported Models:**

Kodak i4250, Kodak i4650, Kodak i4850

# New Features from CD 1.4.1:

- 1. Background Color Smoothing Change to White added with both FW and Host Software are updated
- 2. Updated SVT to allow for enabling driver debugging and log saving from SVT application and not opening the ISIS or TWAIN drivers user interface. Contact Kodak Alaris service organization for more information.

# Improvements from CD 1.4.1:

- 1. Updated SmartTouch Version Must use full CD installation and install updated SmartTouch with updated drivers to have complete functionality
- 2. DIAS-550/PR 26884 ISIS: Can't set sheet counter/printer counter to start at 0
- 3. DIAS-559/PR 26900 ISIS: Flatbed [paper source] not working with Cd v1.4 and Cd v1.5

#### **Known Issues:**

- 1. DIAS-524: PC out of memory error when scanning long (thousands of documents) without disabling.
  - There is a workaround based on customer scanning parameters. Contact the Kodak Alaris service organization for more information.

# **DVD Version 1.4.1 Summary**

**Purpose of Release:** This is a general release to the drivers for the Kodak i4250, i4650 and i4850 scanners which allows the service diagnostic keys for Scan Validation Tool to continue to function after October 12, 2016.

No other changes from DVD 1.4 are included.

# **DVD Version 1.4 Summary**

**Purpose of Release:** This is a general release to the drivers for the Kodak i4250, i4650 and i4850 scanners which adds feature and fixes problems.

Date: August 24, 2016

### Versions:

| TWAIN driver:          | 14.18             |
|------------------------|-------------------|
| ISIS driver:           | 1.1.11606.23003   |
| Scan Validation Tool:  | 12.3              |
| WIA:                   | 6.14              |
| Kodak Capture Pro LE   | 5.2.0.27.12831    |
| Buttonapp (SmartTouch) | 1.8.62.408.160720 |

### **Required Scanner Firmware:**

Scanner Firmware Version:16.08.01(or higher)Note:Required for SmartTouch functionality

### **Supported Operating Systems:**

WINDOWS 7 SP1 WINDOWS 7 SP1 x64 Edition WINDOWS 8 WINDOWS 8 x64 Edition WINDOWS 8.1 WINDOWS 8.1 x64 Edition WINDOWS 10 WINDOWS 10 x64 Edition

#### **Supported Models:**

Kodak i4250, Kodak i4650, Kodak i4850

# New Features from CD 1.1:

- 1. CR 5082-Add Smart Touch support
- 2. CR 5004 & CR 5094 Add "Orange" and "Orange and Red" color dropout
- 3. CR 4868-Save Scanner Logs via ISIS Driver and add debug tab to generating ISIS debug logs
- 4. CR 3602 More than 60 twain profiles can be created
- 5. CR 5103 Support Windows XP through 2016 (TWAIN only), ISIS will not work on Windows XP
- 6. CR 5257 Default shipping language from factory set to English
- 7. CR 5403 Add a Swedish translation of User Manual for i4x50 scanners

#### **Improvements from CD 1.1:**

- 1. CR 5335 ISIS: allow more than 20 consecutive text characters in the imprinter string -
- 2. PR 25626 ISIS Setting IDP to "none" does not turn it off if previously used profile had IDP enabled.
- 3. PR 25671 ISIS: Printing does not turn off if previously used profile had printing enabled
- 4. PR 25625 ISIS driver is missing the default image rotation to. 90,180 or 270 options
- 5. PR 25394 ISIS: Scanner Power Off cannot be disabled
- 6. PR 25064 ISIS: Multiple Translation Issues correct that some strings were not translated
- 7. PR 25423 ISIS: Digital printing is not resetting the counter value for the patch selected on the initial scan
- 8. PR 25445 ISIS: -4769 error on i4x50 with printer counter increment feature enabled
- 9. PR 25169 ISIS: Barcode Image Enhancement Should Be Enabled for Both Perfect Page Profile.
- 10. PR 26714 ISIS: Barcodes Search Area parameters are not being set correctly
- 11. PR 25124 ISIS when starting a scan with pod open the driver does not post an error to the application

- 12. PR 25060 ISIS: Unable to set Multifeed Length Detect to anything greater than 17"
- 13. PR 26771 :Digital Printing with ISIS driver did not allow for Print Rotation to be selected
- 14. PR 25081 ISIS: Some Imprinter Time Selections Produces "Error In Format String" Error Message
- 15. PR 25350 ISIS: Get "Unknown Error -4523" on scan enable when Codabar is barcode type selected

#### **Known Issues:**

- 1. PR 26295 ISIS Interactive Multifeed on last page of batch requires user to press the stop button to get last images
- 2. PR 26138- After Installation on Windows XP the PC will require a reboot
- 3. PR 26793 Smart Touch- Task Short Cut #9 Custom Color File(s) Scan as settings shortcut states "Color Photograph", the system will default to Color Perfect Page if SmartTouch Task #9 is not manually changed
- 4. PR 26795 Smart Touch Buttons on OCP not functioning in Windows XP
- 5. PR 26850 ISIS Multifeed by length is on by default and set to 17 inches in the perfect page profiles.
- 6. PR 26900 ISIS Flatbed [paper source] not working a configuration error occurs

# **DVD Version 1.2 Summary**

**Purpose of Release:** This is a "Hot Fix" to the drivers for the Kodak i4250, i4650 and i4850 scanners.

**Date:** September 10<sup>th</sup>, 2015

### Versions:

| TWAIN driver:         | 14.4           |
|-----------------------|----------------|
| ISIS driver:          | 1.1.11506.4001 |
| Scan Validation Tool: | 11.9           |
| WIA:                  | 5.2            |
| Kodak Capture Pro LE  | 5.5            |
|                       |                |

### **Required Scanner Firmware:**

Scanner Firmware Version:

1.14.0 (or higher)

### **Supported Operating Systems:**

WINDOWS 7 SP1 WINDOWS 7 SP1 x64 Edition WINDOWS 8 WINDOWS 8 x64 Edition WINDOWS 8.1 WINDOWS 8.1 x64 Edition WINDOWS 10 WINDOWS 10 x64 Edition

# **Supported Models:**

Kodak i4250, Kodak i4650, Kodak i4850

# New Features from CD 1.1:

- 1. Windows 10 Support
- 2. Chop/Mag Calibration for China Banking Market

# **Improvements from CD 1.1:**

- 1. User is unable to successfully scan a 360" long document
- 2. Remote FX environment support

### **Known Issues:**

(none)

# ISIS Version 1.1.11508.25001

**Date:** September 10<sup>th</sup>, 2015

### Improvements

- 1. Digital printing is not resetting the counter value for the patch selected on the initial scan
- Fixed, ISIS is now setting digital stamp on/off before setting any imprinter values.
- 2. Getting error -4769 when scanning with enabled Imprinter ISIS driver is now checking for printerindexincrement and printerindexreset on session begin.

# DVD Version 1.1 Summary (Release Notes Updated 2015-07-02)

**Purpose of Release:** This is the initial shipping approved release of drivers for the Kodak i4250, i4650 and i4850 scanners.

**Date:** June 11<sup>th</sup>, 2015

### Versions:

| TWAIN driver:         | 14.3           |
|-----------------------|----------------|
| ISIS driver:          | 1.1.11506.4001 |
| Scan Validation Tool: | 11.6           |
| WIA:                  | 5.1            |
| Kodak Capture Pro LE  | 5.5            |

### **Required Scanner Firmware:**

Scanner Firmware Version: 1.6

1.6.0 (or higher)

### **Supported Operating Systems:**

WINDOWS 7 SP1 WINDOWS 7 SP1 x64 Edition WINDOWS 8 WINDOWS 8 x64 Edition WINDOWS 8.1 WINDOWS 8.1 x64 Edition (note: WINDOWS 10 Certification Coming Soon!)

# **Supported Models:**

Kodak i4250, Kodak i4650, Kodak i4850

# New Features from CD 1.0:

1. N/A

# **Improvements from CD 1.0:**

1. N/A

# Notes:

- (None).

# **Known Issues:**

(none)