

S2085f and S3000 Version 1.9.9.1242

Purpose of Release: This is an updated release of Smart Touch for the Alaris S2085f and S3000 Series Scanners to support the S3120 Max and S3140 Max scanners. Support for Windows 11 and SharePoint Online Modern Authentication has also been added.

Date: March 22, 2022

Required Scanner Software Versions:

S2085f/S3000 CD Version 4.13 or higher

Required Scanner Firmware Versions:

S2085f/S3000 Firmware Version 220201 or higher

Supported Operating Systems:

- WINDOWS 8.1 (32-bit and 64-bit)
- WINDOWS 10 (32-bit and 64-bit)
- WINDOWS 11 (64-bit)
- WINDOWS Server 2012 R2 (64-bit)
- WINDOWS Server 2016 (64-bit)
- WINDOWS Server 2019 (64-bit)
- WINDOWS Server 2022 (64-bit)

Changes and New Features

Security Updates

- Outdated libraries have been updated including replacement of Microsoft libraries and library versions that are no longer supported.
- Updated the OCR engine libraries to the latest version available.
- Full support of TLS 1.2 As IT departments are deprecating support for TLS 1.0 and 1.1, this support becomes necessary for Smart Touch.

***** Operating System Support

- Added support for Windows 11 and Server 2022.
- Dropped support for Windows 7.


Vietnamese OCR Support

• The Vietnamese language is now available for selection when configuring a button shortcut for Searchable PDF output.




SharePoint Online Modern Authentication

- IT organizations are deprecating support for Basic or Legacy authentication
- Modern Authentication encompasses methods such as MFA (Multi-Factor Authentication)




- When enabled, no user credentials are required if the user who logged onto the PC is a domain user on the company network.
 - When the first scan session completes, after Smart Touch is launched, the user may see a taskbar pop-up (and window) that will go away on its own



 During this activity, Smart Touch is getting a Token that can be re-used for all subsequent output processing to SharePoint Online for as long as Smart Touch is running or until the PC is rebooted.

• If the user who logged onto the PC is not a domain user on the company network, then the user will be required to authenticate before the output to SharePoint Online can complete. For example:



Problem Reports Fixed: The following problems have been fixed in this Smart Touch release for the S2085f and S3000 Series Scanners:

- 1. CPSOLSTS-789 Unable to output 100 or more documents using bar code separation
 - When 99 bar code pages or less were scanned at a time, there was no issue. When 100 or more pages were scanned in a single scan session, Smart Touch would display the "Formatting images ..." message and then complete without outputting any of the scanned pages.
- 2. CPSOLSTS-846 Smart Touch can no longer connect to SharePoint Online
 - Error message displayed when attempting to configure a button shortcut for SharePoint Online was "Cloud service unable to connect to URL:".
 - Smart Touch has been updated to fully support TLS 1.2 and can again connect to SharePoint Online.
- 3. CPSOLSTS-813 Cannot create multiple button shortcuts to different SharePoint Online Document Libraries
 - Configuring a second button shortcut to a SharePoint Online document library would automatically change the first button shortcut (which was configured for a different document library) to output to the same document library.

Known Issues:

None



S2085f and S3000 Version 1.9.8.1169

Purpose of Release: This is the initial release of Smart Touch for the Alaris S2085f and S3000 Series Scanners.

Date: August 11, 2020

Required Scanner Software Versions:

S2085f/S3000 CD Version 1.4.0 or higher

Required Scanner Firmware Versions:

S2085f/S3000 Firmware Version 200801 or higher

Supported Operating Systems:

- WINDOWS 7 SP1 (32-bit and 64-bit)
- WINDOWS 8.1 (32-bit and 64-bit)
- WINDOWS 10 (32-bit and 64-bit)
- WINDOWS 2012 Server
- WINDOWS 2012 R2 Server
- WINDOWS Server 2016 Std (64-bit)

Problem Reports Fixed: The following problem reported by Smart Touch users on other Kodak scanner models has been fixed in the initial Smart Touch release for the S2085f and S3000 Series Scanners:

- 1. **CPSOLSTS-690** Can no longer output to Google Drive
 - Google Drive output stopped working in Smart Touch versions 1.9.7 and earlier as Google changed the method by which to authenticate to Google Drive.
 - Smart Touch version 1.9.8 or later is now required to scan and output to Google Drive.
- 2. **CPSOLSTS-684** The Smart Touch name in the Windows Start Menu is **replaced** by inappropriate text (e.g., "NewShortcut16" instead of "Smart Touch") when installing on a German Windows OS.

Known Issues:

None