Installing the IEEE-1394 (FireWire) Card

⚠️ **CAUTION: Refer to your computer's User's Guide for safety-related information.**

IMPORTANT: Use proper precautions to avoid static when you install the IEEE-1394 (FireWire) card.

1. Power down the host computer and all peripherals.
2. Unplug the host computer from its power source.
3. Remove the cover of the host computer.
4. If your computer requires a low profile PCI card, replace the standard height PCI bracket with the low profile PCI bracket that is included with the IEEE-1394 (FireWire) card.
5. Insert the IEEE-1394 (FireWire) card into an open PCI slot and secure the card.

NOTE: Do not connect the IEEE-1394 (FireWire) cable to the scanner at this time. Refer to the *Kodak* i600 Series Scanners User's Guide for scanner installation instructions.

6. Re-attach the cover of the host computer.
7. Plug the host computer's power cord into a power outlet.
8. Power up the host computer and any peripherals you previously powered down.

   A dialog box stating that an IEEE-1394 Host Controller has been found may appear on the host computer screen.

9. Follow the on-screen instructions and select the default settings to complete the installation.

COMMERCIAL IMAGING **Kodak**