Kodak alaris

E1000 Series Scanner Firmware Release Notes

Firmware Version 210104 Summary

Purpose of Release: This is the updated release of the firmware for the E1025 and E1035 for a scanner hardware (Main Board) change, the firmware supports both version of hardware configurations.

Date: January 4, 2021

Recommended Host Driver Version:
KODAK E1000 Driver Installation Disk Version: 4.2.1

Firmware Update Process:
With an E1000 scanner connected and the drivers installed on the host computer, download and run **e1000_210104_Firmware.exe** to update the firmware. The firmware release can be found on either the E1025 or E1035 support page:

https://support.alarisworld.com/e1025-scanner#Software

https://support.alarisworld.com/e1035-scanner#Software

New Features for Firmware 210104:

1. Support both original and updated hardware configurations
    a. There are no functional differences between the hardware configuration changes and V210104 supports both configurations.

Improvements for Firmware 210401:
1. none

Known Issues:
1. none

Notes:

If installing the firmware on Windows 7/8/10 PC a "Program Compatibility Assistant" message may be displayed. This is normal. Click "This Program installed correctly" to continue.

Kodak alaris

E1000 Series Scanner Firmware Release Notes

Firmware Version 200501 Summary

Purpose of Release: This is the updated release of the firmware for the E1025 and E1035 to change the Branding from Alaris to Kodak.

Date: May 1, 2020

Recommended Host Driver Version:
KODAK E1000 Driver Installation Disk Version: 3.3

Firmware Update Process:
With an E1000 scanner connected and the drivers installed on the host computer, run **e1000_200501_Firmware.exe** to update the firmware.

New Features for Firmware 200501:

1. Updates for Branding change from Alaris to Kodak
   a. USB Product descriptor changed to KODAK E10X5 scanners

Improvements for Firmware 200502:
1. none

Known Issues:
1. none

Notes:
If installing the firmware on Windows 7/8/10 PC a "Program Compatibility Assistant" message may be displayed. This is normal. Click "This Program installed correctly" to continue.

E1000 Series Scanner Firmware Release Notes

Firmware Version 190201 Summary

Purpose of Release: This is the initial release of firmware for the E1025 and E1035 scanners.

Date: February 1, 2019

Recommended Host Driver Version:
   E1000 Driver Installation Disk Version: 01.08.00

New Features from Firmware xx.xx.xx:
   1. initial release of firmware

Improvements from FW xx.xx.xx:
   1. initial release of firmware

Known Issues:
   1. none

Notes:

If installing the firmware on Windows 7/8/10 PC a "Program Compatibility Assistant" message may be displayed. This is normal. Click "This Program installed correctly" to continue.