

# Kodak i1150/i1180/i1190/i1190E Scanner Software and Firmware Release Notes

## Version CD 2.16 Summary

**Purpose of Release:** This is a CPE release of drivers for the Kodak i1150 Scanner.

Note: When installing a Kodak i1150 Scanner on a host PC for the first time the Full Install CD (shipped with the scanner) must be used. If the InstallSoftware\_v2.xx.exe driver installer is used for a new installation the Kodak Smart Touch application will not be installed. The InstallSoftware\_v2.xx.exe may be used to update a host PC that used an Install CD Version 1.xx for its first install.

<b>Date:</b>	<b>January 9, 2017</b>
<b>CD Version:</b>	<b>2.16</b>
<b>Firmware</b>	<b>1.35 (separate file, not part of CD) for i1150/i1190</b>
<b>Firmware</b>	<b>1.32 (separate file, not part of CD) for i1180/i1190E</b>
<b>Twain:</b>	<b>14.5</b>
<b>Driver.dll:</b>	<b>4.8</b>
<b>Twaingui:</b>	<b>8.1</b>
<b>Hippo.dll:</b>	<b>52.30</b>
<b>Device.dll:</b>	<b>4.4</b>
<b>DeviceManager.dll:</b>	<b>1.17</b>
<b>ISIS driver:</b>	<b>1.1.11609.30001</b>
<b>Smart Touch App</b>	<b>1.8.68.475</b>

### New Driver Features:

1. CR 5370 - Add QR Barcode reading
2. CR 5276 - Add 64-bit TWAIN driver
3. CR 5119 - Do not Install ISIS on Windows XP Operating System computers

### Smart Touch Features/Fixes:

1. PR 26539 - When scanner wakes from sleep mode, it no longer connects
2. CPSOLSTS-101/202 - Smart Touch not sending paper source information
3. PR 26223 - When you set the searchable PDF of the i1190 SmartTouch it shows Arabic as an option
4. CPSOLSTS-163 - Folder permissions are being changed when users are scanning
5. CPSOLSTS-164 - SmartTouch won't install when a folder redirection of the users' home directories to a server has been moved
6. CPSOLSTS-166 - The date is being repeated in the filename string
7. CPSOLSTS-186 - SmartTouch upgrade does not always happen correctly when running silently

**Driver Issues Fixed:**

1. PR 26946 - i1150 when scanning 2D barcode with TWAIN or ISIS Driver
2. PR 26840 - problem when scanning dark hard cards (credit cards)
3. PR 25842 - Unable to communicate with scanner after PC comes out of Sleep Mode
4. PR 25701 - When using Blank page removal, an image that is not blank is being deleted
5. DIAS-507- WIA version not updating with i11xx CD v2.14 upgrade [Smart Touch scanner buttons don't work, but Smart Touch in system tray works]
6. DIAS-889 - Smart Touch Buttons on OCP not functioning in Windows XP

**Firmware Issues Fixed:**

1. DIAS-478: Scanner errors on OCP can be over written on startup
2. CD 5390 - Increase the feeder clutch on time from 10mm to 20mm - also in FW 1.32

**Known Issues:**

None

## **Kodak i11xx Series Scanners Software Release Notes Version CD 2.07.01 Summary**

**Purpose of Release:** This is a LPO release to the drivers for the Kodak i3000 scanners which allows the locking of a specific customer application to occur such that the TWAIN driver will only work with this one specific application.

**Date:** November 9, 2016  
**CD Version:** 2.07.01

## **Kodak i1150 Scanner Software Release Notes**

### **Version CD 2.07 Summary**

**Purpose of Release:** This is a CSM release of drivers for the Kodak i1150 Scanner.

Note: When installing a Kodak i1150 Scanner on a host PC for the first time the Full Install CD (shipped with the scanner) must be used. If the InstallSoftware\_v2.xx.exe driver installer is used for a new installation the Kodak Smart Touch application will not be installed. The InstallSoftware\_v2.xx.exe may be used to update a host PC that used an Install CD Version 1.xx for its first install.

**Date:** January 30<sup>th</sup>, 2016  
**CD Version:** 2.07  
**Firmware:** 1.21  
**Twain:** 14.2  
**Driver.dll:** 4.3  
**Twaingui:** 6.7  
**Hippo.dll:** 52.26  
**Device.dll:** 4.1  
**DeviceManager.dll:** 1.14  
**ISIS driver:** 1.1.11512.4001  
**Smart Touch App:** 1.8.43.247

### **New Driver Features:**

4. Increase to 30ppm from 25ppm
5. Change to default profile: Turned off Hole fill and Streak Removal

### **Smart Touch Features**

1. None

### **Issues Fixed:**

7. None

### **Known Issues:**

None

## Version CD 2.01 Summary

**Purpose of Release:** This is a CSM release of drivers for the Kodak i1150 Scanner.

Note: When installing a Kodak i1150 Scanners on a host PC for the first time the Full Install CD (shipped with the scanner) must be used. If the InstallSoftware\_v2.xx.exe driver installer is used for a new installation the Kodak Smart Touch application will not be installed. The InstallSoftware\_v2.xx.exe may be used to update a host PC that used an Install CD Version 1.xx for its first install.

<b>Date:</b>	<b>November 18, 2014</b>
<b>CD Version:</b>	<b>2.01</b>
<b>Firmware</b>	<b>1.04.02</b>
<b>Twain:</b>	<b>13.1</b>
<b>Driver.dll:</b>	<b>13.6</b>
<b>Twaingui:</b>	<b>5.36</b>
<b>Hippo.dll:</b>	<b>52.24</b>
<b>Device.dll:</b>	<b>4.2</b>
<b>DeviceManager.dll:</b>	<b>1.9</b>
<b>ISIS driver:</b>	<b>1.1.11404.29001</b>
<b>Smart Touch App</b>	<b>1.8.18.104</b>

### New Driver Features:

6. Add error message for no image data
7. Mac Drivers Available
8. Mac - PageManager - Scan Button was launched and added to the system tray
9. Add JPEG and G4 Compressions to PageManager
10. Expand Linux support to 64-bit for Ubuntu 14.04 (LTS)
11. Develop Mag Adjustment Tool Mag for China Bank customers

### Smart Touch Features

1. Have a silent installer option for Smart Touch patch (web) installer
2. Ability to not create a copy of the file on the PC when emailing a document
3. Add the name WebDAV to Custom Cloud
4. Add 'create folder' icon to configure cloud storage screen
5. Support Scan to Google Drive (CloudStorage)
6. Hide 'delete file after sending' option when change to non-mail destination

### Issues Fixed:

8. None

### Known Issues:

None