

# **Kodak i5000V Series Scanners Software Release Notes**

## **Version CD 3.0 Summary**

**Purpose of Release:** This release is for an update to Kofax VRS 5.1.1 Kodak OEM for the Kodak i5x50v Scanners and to maintain compliance with US Energy Star 3.0 standard.

**Date:** October 3, 2017

**Instructions for installing drivers using the ISO file:**

For Windows 8.1 and 10 OS, mount the ISO file as a drive. (right click on the ISO file and select Mount). If Mount is not available in the list of options. Right click on the ISO file, select properties and change the Opens With to Windows Explorer and click OK. Mount will now appear with the right click of the ISO file.

For Windows 7 OS, either the ISO file has to be mounted as a drive or the ISO contents extracted to a folder using a 3<sup>rd</sup> party software tool. Software Tool providers (tools have not been tested and are not supported by the Kodak Alaris team, customers have reported that (7-zip, winrar, winiso) offer such capability.

### **Versions:**

VRS (Kodak OEM)	5.1.1.13.0.2092
TWAIN driver:	18.0
ISIS driver:	(Not included)
Scan Validation Tool:	17.2.1
WIA:	9.0
Firmware:	(Not Included) use with 06.03.09

### **Supported Models:**

Kodak i5250V  
Kodak i5650V  
Kodak i5200V (not QA Tested, new features not supported)  
Kodak i5600V (not QA Tested, new features not supported)  
Kodak i9000 (Ngenuity) (not QA Tested, new features not supported)

### **Changed Kofax V5.1.1 Features from CD 2.3:**

1. Support US Energy Star 3.0 standard, the maximum power off timeout is now 120 minutes.

### **Kodak Features from CD 2.2:**

1. none

**Notes:** Navigating in the ISO to the drivers/VRS folder one can execute just the Kofax installer which has fixes for other Kodak products with Kofax support both in hardware and software VRS.

**Known Issues:** (none)

# **Kodak i5000V Series Scanners Software Release Notes**

## **Version CD 2.3 Summary**

**Purpose of Release:** This release is for a new Kofax VRS 5.1.1 Kodak OEM for the Kodak i5x50v Scanners and service diagnostic updates when using SVT. The main intent of this release is to support the new features and functions for the i5250V and i5650V Scanners with a Kodak OEM, VRS Elite version 5.1.1

**Date:** January 3, 2017

### **Instructions for installing drivers using the ISO file:**

For Windows 8.1 and 10 OS, mount the ISO file as a drive. (right click on the ISO file and select Mount). If Mount is not available in the list of option. Right click on the ISO file, select properties and change the Opens With to Windows Explorer and click OK. Mount will now appear with the right click of the ISO file.

For Windows 7 OS, either the ISO file has to be mounted as a drive or the ISO contents extracted to a folder using a 3<sup>rd</sup> party software tool. Software Tool providers (tools have not been tested and are not supported by the Kodak Alaris team, customers have reported that (7-zip, winrar, winiso) offer such capability.

### **Versions:**

VRS (Kodak OEM)	5.1.1.6.0.1957
TWAIN driver:	14.15.1
ISIS driver:	(Not included)
Scan Validation Tool:	14.4
WIA:	6.6
Firmware:	(Not Included) use with 06.03.03

### **Supported Models:**

Kodak i5250V  
Kodak i5650V  
Kodak i5200V (not QA Tested, new features not supported)  
Kodak i5600V (not QA Tested, new features not supported)  
Kodak i9000 (Ngenuity) (not QA Tested, new features not supported)

### **New Kofax V5.1.1 Features from CD 2.2:**

1. Configurable page detection settings
2. Programmatic controls for ImageAddress with VRS TWAIN data source
3. TIFF Image Name and Assigned Profile columns added to Auto Profile log
4. Ability of VRS clients to select Shared Profiles from separate, configurable subfolders
5. Define fixed dpi to improve performance of Auto Profile document classification
6. Enhanced update process for VRS component installers

### **New Kodak Features from CD 2.2:**

2. Kodak SVT service diagnostics now allow image calibration with a level 1 daily password

**Notes:** (none)

**Known Issues:** (none)

**Kodak i5000V Series Scanners Software Release Notes**

# **Kodak i5000V Series Scanners Software Release Notes**

## **DVD Version 2.2 Summary**

**Purpose of Release:** This is a general release to the drivers for the Kodak i5250V, i5650V scanners which allows the service diagnostic keys for Scan Validation Tool to continue to function after October 12, 2016.

No other changes from DVD 2.2 are included.

### **Instructions for installing drivers using the ISO file:**

For Windows 8.1 and 10 OS, mount the ISO file as a drive. (right click on the ISO file and select Mount)

For Windows 7 OS, either the ISO file has to be mounted as a drive or the ISO contents extracted to a folder using a 3<sup>rd</sup> party software tool. Software Tool providers (tools have not been tested and are not supported by the Kodak Alaris team, customers have reported that (7-zip, winrar, winiso) offer such capability.

**Date:** October 12, 2016

### **Versions (changed from last release):**

Scan Validation Tool: 12.3.1

# **Kodak i5000V Series Scanners Software Release Notes**

## **Version CD 2.1 Summary**

**Purpose of Release:** This is the first release of drivers for the Kodak i5x50v Scanners. The main intent of this release is to support the new features and functions for the i5250V and i5650V Scanners with VRS Elite version 5.1

**Date:** June 6, 2016

### **Versions:**

VRS (Kodak OEM)	5.1.0.0.1206 Professional
TWAIN driver:	14.6
ISIS driver:	(Not included)
Scan Validation Tool:	12.2
WIA:	6.6
Firmware:	(Not Included) use with 05.11.5

### **Supported Models:**

Kodak i5250V  
Kodak i5650V  
Kodak i5200V (not QA Tested, new features not supported)  
Kodak i5600V (not QA Tested, new features not supported)  
Kodak i9000 (Ngenuity) (not QA Tested, new features not supported)

### **New Features from CD 1.4:** (i5x50V only.)

1. Intelligent Printing – Patch Counting
2. Intelligent Document Protection
3. Patch Configurator
4. Hold Multifeeds at Exit Nip
5. Variable Print Size
6. Additional Date Time print options
7. Support Orange and Orange/Red ECDO Colors
8. Support 500 DPI image resolution

### **Improvements from CD 1.4:**

3. See new Features

### **Notes:**

- The testing for this release was done with scanner Firmware 05.11.05.
- The i5x50V scanner was designed specifically to support Kofax VRS. There is no ISIS “direct” ISIS driver installed. The Kodak direct TWAIN driver and SVT are included only for diagnostic support. The Kodak i5x50V scanners performance is severely limited when using the direct TWAIN driver.
- The i5x50V scanner should only be used with applications that support Kofax VRS.

### **Known Issues:**

(none)

# **Kodak i5000V Series Scanners Software Release Notes**

## **Version CD 1.4 Summary**

**Purpose of Release:** This is the second release of drivers for the Kodak i5000v Scanners. The main intent of this release is to support Windows 8 which required VRS Elite version 5.1.0.

**Date:** May 29<sup>st</sup>, 2014

### **Versions:**

VRS (Kodak OEM)	5.1.0474 Professional
TWAIN driver:	12.1
ISIS driver:	(Not included)
Scan Validation Tool:	9.25
WIA:	3.8
Firmware:	3.14.5

### **Supported Models:**

Kodak i5200V  
Kodak i5600V

**New Features from CD 1.0:** (See updated User Documentation for more details.)

9. Support for Windows 8
10. Update to VRS 5.1

### **Improvements from CD 1.0:**

4. The Kodak OEM VRS 5.1.0 Professional version provided in this release includes all of the updates to Kofax VRS Elite 5.1.0 R2 (5.1.0078 ) and more. Please refer to the Kofax VRS 5.1.0 Release Notes on the Kofax web site for more information.
5. Updated User Documentation

### **Notes:**

- The testing for this release was done with scanner Firmware 3.14.5. Kodak i5000V scanners with older versions of firmware should be updated to this version when installing this release.
- The i5000V scanner was designed specifically to support Kofax VRS. There is no ISIS “direct” ISIS driver installed. The Kodak direct TWAIN driver and SVT are included only for diagnostic support. The Kodak i5000V scanners performance is severely limited when using the direct TWAIN driver.
- The i5000V scanner should only be used with applications that support Kofax VRS.

### **Known Issues:**

(none)

# **Kodak i5000V Series Scanners Software Release Notes**

## **Version CD 1.0 Summary**

**Purpose of Release:** This is the initial release of drivers for the Kodak i5000v Scanners.

**Date:** March 1<sup>st</sup>, 2012

### **Versions:**

VRS (Kodak OEM)	5.0.953 Professional
TWAIN driver:	11.9
ISIS driver:	(Not included)
Scan Validation Tool:	8.9
WIA:	1.17

### **Supported Models:**

Kodak i5200V  
Kodak i5600V

### **Notes:**

(none)