

S2000f/S3000 Series Scanner ISIS Driver Release Notes

ISIS Driver Version kas3000_1.0.12008.8001

Purpose of Release: : This update corrects 1 issue found with the ISIS driver related to the Orientation and Y-Position settings in the Stamp Layout tab do not get applied to the physical imprinter

Instructions for installing ISIS driver:

The installer is installed after the full drivers installed V1.4 has previously been installed on the computer. Then unzip the file kas3000_1.0.12008.8001.zip and execute the file setup.exe

Date: August 12,2020

Versions (after the CD and this ISIS driver are installed):

CD Version:	1.4
TWAIN:	20.2
Driver:	1.11
Driverui:	12.11
Device:	1.15
KAScannerService:	5.2
DeviceManager:	1.6
ISIS driver:	1.0.12008.11001
WIA:	12.6
Scan Validation Tool:	19.1

Required Scanner Firmware:

Scanner Firmware Version: 200801

Supported Models:

Kodak S2085f and all Kodak S3xxxxy scanners

New Features for CD 1.4:

1. none

Improvements:

Problem: The Orientation and Y-Position settings in the Stamp Layout tab do not get applied to the physical imprinter.

Solution: synchronization of the digital and physical imprinters upon exit of this tab

Notes:

None:

Known Issues:

1. None