

Kodak i900 Series Scanners Windows Drivers Release Notes

Version CD 7.1 Summary

Purpose of Release: This is a general CPE release of the installation CD for the Kodak SCANMATE i900 Series Scanner.

Update for December 2022 is that Windows 10 and 11 22H2 releases are supported with no changes required.

Instructions for installing drivers using the ISO file:

For Windows 8.1 and 10 OS, mount the ISO file as a drive. (right click on the ISO file and select Mount)

For Windows 7 OS, either the ISO file has to be mounted as a drive or the ISO contents extracted to a folder using a 3rd party software tool. Software Tool providers (tools have not been tested and are not supported by the Kodak Alaris team, customers have reported that (7-zip, winrar, winiso) offer such capability.

Date: July 26, 2019

Versions:

TWAIN	18.0
Driver	7.1
HIPPO	52.15
Device	7.0
ISIS	2.0.11907.22001
SVT	17.2.1
WIA/STI	9.0

TWAIN Standard: 2.4

Operating Systems (not a complete list of supported OS, see specifications page):

WINDOWS 11 (Original release 21H2 and 22H2)

WINDOWS 7 SP1 x64 Edition (no longer tested as of March 2022)

WINDOWS 8.1 (64-bit)

WINDOWS 10 (32-bit) up to and including 22H2

WINDOWS 10 (64-bit) up to and including 22H2

(Linux - (Intel/AMD x86/64 bit processors only))

Ubuntu 18.04 64-bit

Ubuntu 16.04 64-bit and 32-bit

Open SUSE 11.3 (i586) 32-bit

Open SUSE LEAP 15.1 64-bit

SUSE Linux Enterprise Desktop 12.2 64-bit

SUSE Linux Enterprise Desktop 15 SP1 for 64 bit

Neokylin-NKLD-V7_U2-ZX64-REL-build54

NeoKylin-Live-Desktop-6.0-x86_64-B060-20160822

NeoKylin-Linux-Desktop-6.0-x86_64-B045-20141201 64-bit

Kodak i900 Series Scanners Windows Drivers Release Notes

NeoKylin-Linux-Desktop-6.0 i586 32-bit

Change Requests Implemented:

1. DIAS-1824 – Support US Energy Star 3.0 standard – Maximum limit is 120 minutes

Problem Reports Implemented:

1. None

Known Issues:

None

NOTES:

- 1) Installing the scanner drivers will install the latest SVT (Scanner Validation Tool), TWAIN Data Source, the NEW ISIS Driver and the latest WIA/STI drivers for the SCANMATE i900 Series Scanner.
- 2) IMPORTANT – Turn off and unplug the scanner from your PC when installing the new drivers.
- 3) User guides are only installed with the full version of the download. Please see the Manuals & Guides section of the product web page for the latest version.
- 4) The Smart Touch application is only installed with an internet download.

Kodak i900 Series Scanners Windows Drivers Release Notes

Version CD 5.3 Summary

Purpose of Release: This is a CPE release of the installation CD for the Kodak SCANMATE i900 Series Scanner with changes to work with Windows 10 V1709 update (Fall 2017).

Instructions for installing drivers using the ISO file:

For Windows 8.1 and 10 OS, mount the ISO file as a drive. (right click on the ISO file and select Mount)

For Windows 7 OS, either the ISO file has to be mounted as a drive or the ISO contents extracted to a folder using a 3rd party software tool. Software Tool providers (tools have not been tested and are not supported by the Kodak Alaris team, customers have reported that (7-zip, winrar, winiso) offer such capability.

Date: March 30, 2018

Versions:

TWAIN	16.5
Driver	5.3
HIPPO	52.13
Device	5.2
ISIS	2.0.11304.29001
SVT	14.21
WIA/STI	1.3

Supported Operating Systems:

- WINDOWS Vista SP1 (32-bit and 64-bit)
- WINDOWS 7 (32-bit and 64-bit)
- WINDOWS 8 (32-bit and 64-bit)
- WINDOWS 8.1 (32-bit and 64-bit)
- WINDOWS 10 (32-bit and 64-bit)

Change Requests Implemented:

2. None

Problem Reports Implemented:

2. DIAS-1441, DIAS-1452 – Twain Driver will not connect with Windows 10 Creator v1709
3. CPSOLSTS-237 –Smart Touch buttons do not work with Windows 10 Creator v1709
4. DIAS-1478 – Installation shows "not enough space" with 3TB harddrive

Known Issues:

None

Kodak i900 Series Scanners Windows Drivers Release Notes

NOTES:

- 5) Dependencies: [Microsoft .Net 2.0 and Microsoft Installer 3.x](#)
- 6) Installing the scanner drivers will install the latest SVT (Scanner Validation Tool), TWAIN Data Source, the NEW ISIS Driver and the latest WIA/STI drivers for the SCANMATE i900 Series Scanner.
- 7) **IMPORTANT** – Turn off and unplug the scanner from your PC when installing the new drivers.
- 8) User guides are only installed with the full version of the download. Please see the Manuals & Guides section of the product web page for the latest version.
- 9) The Smart Touch application is only installed with an internet download.

Kodak i900 Series Scanners Windows Drivers Release Notes

Version CD 4.6 Summary

Purpose of Release: This is a CPE release of the installation CD for the Kodak SCANMATE i900 Series Scanner.

Instructions for installing drivers using the ISO file:

For Windows 8.1 and 10 OS, mount the ISO file as a drive. (right click on the ISO file and select Mount)

For Windows 7 OS, either the ISO file has to be mounted as a drive or the ISO contents extracted to a folder using a 3rd party software tool. Software Tool providers (tools have not been tested and are not supported by the Kodak Alaris team, customers have reported that (7-zip, winrar, winiso) offer such capability.

Date: September 11, 2017

Versions:

ISIS - 2.0.11304.29001

SVT – 14.13

TWAIN – 14.1

WIA/STI - 1.0 (signed)

Supported Operating Systems:

- WINDOWS Vista SP1 (32-bit and 64-bit)
- WINDOWS 7 (32-bit and 64-bit)
- WINDOWS 8 (32-bit and 64-bit)
- WINDOWS 8.1 (32-bit and 64-bit)
- WINDOWS 10 (32-bit and 64-bit)

Change Requests Implemented:

3. DIAS-1225 –Remove SmartTouch from installation media
4. DIAS-1226 – Remove Capture Pro LE from installation media
5. DIAS-1284 – Update Installer with link to Smart Touch and Capture Pro LE internet downloadable files.
6. CR5315 - add 64-bit TWAIN drivers

Problem Reports Implemented:

1. PR25045 – Improve VTM scanning with i940

Known Issues:

None

NOTES:

Kodak i900 Series Scanners Windows Drivers Release Notes

- 10) Dependencies: [Microsoft .Net 2.0 and Microsoft Installer 3.x](#)
- 11) Note: When installing a Kodak SCANMATE i940 scanner on a host PC for the first time the Full Install CD (shipped with the scanner) must be used.
- 12) Installing the scanner drivers will install the latest SVT (Scanner Validation Tool), TWAIN Data Source, the NEW ISIS Driver and the latest WIA/STI drivers for the SCANMATE i900 Series Scanner.
- 13) IMPORTANT – Turn off and unplug the scanner from your PC when installing the new drivers.
- 14) User guides are only installed with the full version of the download. Please see the Manuals & Guides section of the product web page for the latest version.
- 15) The Smart Touch application is only installed with a internet download.

Kodak i900 Series Scanners Windows Drivers Release Notes

Version CD 4.0 Summary

Purpose of Release: This is a CPE release of drivers for the Kodak SCANMATE i940 Scanner.

Note: When installing a Kodak SCANMATE i940 scanner on a host PC for the first time the Full Install CD (shipped with the scanner) must be used. If the InstallSoftware_i900_v2.xx.exe driver installer is used for a new installation the Kodak Smart Touch application will not be installed. The InstallSoftware_i900_v2.xx.exe may be used to update a host PC that used an Install CD Version 1.0 for its first install.

Date: August 14, 2015

Versions:

ISIS - 2.0.11304.29001

SVT – 11.9

TWAIN – 14.1

WIA/STI - 1.0 (signed)

Smart Touch – 1.8.39

Change Requests Implemented:

7. Support for Windows 10
8. Support for Arabic in TWAIN GUI and Smart Touch
9. New Installation Wizard
10. MAC - Ability to set the PDF file size
11. MAC – Support MAC OSX 10.10

Known Issues:

None