

SmartTouch for Kodak i1100WN Series Scanners Release Notes

Version 1.9.7.1059 Summary

Purpose of Release: This is a maintenance release for internet download of the SmartTouch application for the Kodak i1100WN Series Scanners.

Date: April 10, 2019

Compatible Scanner Versions:
Host CD 2.0 (WINDOWS drivers)

Supported Operating Systems:

- WINDOWS 7 (32-bit and 64-bit)
- WINDOWS 8 (32-bit and 64-bit)
- WINDOWS 8.1 (32-bit and 64-bit)
- WINDOWS 10 (32-bit and 64-bit)

Problem Reports Fixed:

1. **CPSOLSTS-413** – “**Failed to format images**” error when scanning many documents and outputting all scanned images into one Searchable PDF file. The supported number of images that can be output to one Searchable PDF file, scanned at 200 DPI Black & White, Grayscale, or Color, has been increased to **500 images** (i.e., 250 physical pages scanned in duplex mode or 500 physical pages scanned in simplex mode).

Known Issues:

None

NOTES:

- Running the installer for this latest version of SmartTouch will upgrade an existing installation and keep all current SmartTouch button assignments.
- After upgrading to a 1.9.x release of SmartTouch, if the SmartTouch Import/Export tool was used to replicate SmartTouch settings across multiple PCs, and the option **All users share the same settings** is chosen, the SmartTouch settings will be moved to the following directory on the PC:

C:\Users\Public\Documents\Smart Touch\i11xxwn

- **New Installation or Upgrade:** User will be prompted to “Send usage data” or “Do not send usage data”. If the user consents during the installation or upgrade of SmartTouch, and the PC has internet access, usage data will be collected via Google Analytics.

SmartTouch for Kodak i1100WN Series Scanners Release Notes

Version 1.9.5.974 Summary

Purpose of Release: This is a maintenance release for internet download of the SmartTouch application for the Kodak i1100WN Series Scanners.

Date: October 20, 2018

Compatible Scanner Versions:

Host CD 2.0 (WINDOWS drivers)

Supported Operating Systems:

- WINDOWS 7 (32-bit and 64-bit)
- WINDOWS 8 (32-bit and 64-bit)
- WINDOWS 8.1 (32-bit and 64-bit)
- WINDOWS 10 (32-bit and 64-bit)

Problem Reports Fixed:

1. [CPSOLSTS-514](#) – Renaming the default Smart Touch button shortcuts does not work. The user interface allows you to attempt to rename a button shortcut, but any changes are not saved. This problem was new in the 1.9.5.941 release and is now fixed.

Change Requests Implemented:

None

Known Issues:

None

NOTES:

- On WINDOWS 10 PCs, Host CD 2.0 must be installed to ensure proper connectivity from SmartTouch to the i1100WN Scanner as well as proper display and functioning of the Scanner Button assignments configured in SmartTouch.